



BOTTOM CORNERS MAY BE
CLIPPED 50 x 50 TO AID
POST DRIVING.

1994

WEAK POST SOIL PLATE

PLS01

SHEET NO.

REF. NO.

1 of 2

P-4-76